Technical Data Sheet

Overall Series

Description

Diamond Overall Primer Filler Putty is ideal for filling cracks, holes, gaps in plaster, wood and other building materials. It forms an ideal base to give a durable, long-lasting and smooth finish.

Recommended Use

To fill pores and imperfections of plaster, concrete and gypsum surfaces. The product is easy to apply with applicator and provides ideal finish for subsequent coats.

Physical Properties

Colour White Finish Matt Solids (vol %)* 42 ± 2

Flash Point N/A - Water Based

Specific Gravity 1.50

Film Thickness and Spreading Rate

Recommended Film Thickness According to Surface

(typically 100 microns dft) (Normally 4-5 m² / Kg / Coat)

Surface Preparation

Spreading Rate

All loose material including loose plaster, cement splashes, old paint, dust, etc. must be thoroughly removed. New plaster/concrete must be fully cured.

Condition During Application

The temperature of the substrate should be min. 3°C above the dew point of the air temperature and relative humidity not more than 70% measured in the vicinity of the substrate. Good ventilation is necessary when the paint is used in confined spaces.

Application

Application Methods Putty Knife / Trowel / Scraper

Cleaning Clean Water

Thinning Not Required / Ready to Use

Drying Time

Temperature	Dry to Touch	Dry to Handle	Recoating Time
25 °C	2 hours	4 hours	4 hours
35 °C	1 hour	3 hours	3 hours

Typical Paint System

On Plaster / Concrete

Diamond Overall Water Based Acrylic Primer
Diamond Overall Primer Filler Putty
2 Coats
Emulsions Top Coat
2-3 Coats

Overall Primer Filler Putty



Storage

The product must be stored in accordance to the national regulations. The product should be kept in a well-ventilated place, protected from the heat and direct sunlight. The containers must be kept tightly closed.

Handling

Handle with care. Stirr well before use.t.

Packing Size

1.25kg, 5kgs and 20kgs.

Health and Safety

Material health and safety data sheet is available upon request. Please observe the precautionary notice displayed on the container. Ensure proper ventilation during application and drying of paint. Avoid inhalation of paint mist/vapours and skin contact. Spillage of paint on skin should immediately be removed with suitable cleanser soap and water. Eyes should be well flushed with water and immediate medical attention should be sought.

